


Repair of the lid on the heat storage



At the beginning..





As it looked before.





As it looked before.

Lots of puddles all over






XPS insulation arrives






Preparation for patch welding






100 m³ Leca is refilled from 2.5 m³ bags





Filling a larger hole





Filling a larger hole


There have been a number of air pockets that have been emptied of air.





Welding of the old lid after filling Leca






First "sod".


We just need to figure out how to get started.






Plastic nails are cut in the upper insulation to hold the layers together.






The first approx. 1000 sandbags are ready






The sandbags move as you reach and weld the top cover





The new insulation





Thermal photo

The photo was taken on Sept. 23 early in the morning.



Calculation of heat loss 2019 Estimated heat loss Actuel heat loss Increased heat loss - 6900-1300 Estimated heat loss in % =Actuel heat loss in % Loss by N—gas price Dkk. 300,-/MWh =Repair costs = Price reduction per. household on 18,1 MWh/år = Or approx. 10% reduction in total.

1300 MWh/year 6900 MWh/year 5600 MWh/year

10% 53% 1.680.000 Dkk./year 6.000.000 Dkk. ca. 1.800,- Dkk./year

